


000211



NOTES

UNDERGROUND UTILITY SERVICE

THIS SURVEY WAS PREPARED WITHOUT BENEFIT OF A TITLE REPORT PROPERTY MAY BE SUBJECT TO EASEMENTS & SERVITUDES OF RECORD

PROPERTY SHOWN HEREON IS LOCATED IN ZONE X AS SHOWN ON FLOOD INSURANCE RATE COMMUNITY NUMBER 510182, MAP NUMBER 51199C0285C, EFFECTIVE DATE JUNE 16, 2009


SYMBOLS :

- PIPE FOUND
- IRON ROD SET
- IRON ROD FOUND
- CONC MONUMENT

Donald W. Davis
 I HEREBY CERTIFY THAT THE SURVEY REPRESENTED BY THIS PLAT WAS MADE BY ME ON THIS DATE AND IS CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF THERE ARE NO ENCROACHMENTS OF BUILDINGS UNLESS SHOWN HEREON

DAVIS & ASSOCIATES, P.C.
 SURVEYORS - PLANNERS
 YORK COUNTY, VIRGINIA

KISKIAC TURN
 50' R/W



JOB LOCATION #102 KISKIAC TURN

PLAT OF THE PROPERTY OF
DONALD G. CURRY & MARY B. CURRY
 LOT 3
 SUBDIVISION PLAT OF
RUNNING MAN
 SECTION FIVE-A
 COUNTY OF YORK, VIRGINIA
 PLAT BOOK 11, PAGE 213

GPIN: 403D-3926-1695

000212

VIRGINIA: In the Clerk's Office of the York County -
Poquoson Circuit Court, the 17th day of
April, 2014. This deed was
presented with the certificate annexed and admitted
to record at 1:26 o'clock p M.

Teste: LYNN S. MENDIBUR, CLERK
By: Christina H Ewitt DC

0001