


IRON FOUND

IRON FOUND

177'

Parcel # B



1077.77'

Part of Farm #8

IRON SET

N 10° W

139.25'

1250'

IRON SET

1250'

S 80° 30' W

172.23'

Parcel # A

172.23'

FARM #7

Richard Wallace.

IRON FOUND

40.75'

IRON SET

133.25'

S 10° E

IRON SET

Greenwald Ave.

40'

Survey of part of the Northerly 5 Acres of Farm #8 of Fairview Farms situated in the Grafton District, York County Virginia and being part of the Waterview Farm. Survey for Mrs Joseph Wallace. Ralph D. Pitt, Engineer. Scale 1"=400' Jan 22 1956